


## Length Apparatus-Length Gauge



This gage is used to measure the length of aggregate.



Model	QRAG-1001
Material	Stainless, wooden support
Gauge	2"~1 1/2", 1 1/2"~1 1/4", 1 3/4"~1 1/2", 1 1/2"~3/8", 3/8"~1/4"
Weight (kg)	1

## Flakiness Apparatus-Thickness Gauge



This gage is used to measure the flatness of aggregate.




Model	QRAG-1002
Material	Stainless
Gauge	3/8"~1/4", 1/2"~3/8", 3/4"~1/2", 1"~3/4", 1 1/4"~1", 1 1/2"~1 1/4", 2"~1 1/2", 2 1/2"~2"
Weight (kg)	0.5

## Rock Point Load Tester



This tester is used to measure strength of natural rock or the core sample.



Model	QRRPL-1001
Capacity	50 kN
Load Sensor	Pressure cell
Display	Digital
Operation	Passive Oil Press
Pump	Manual Hydraulic
Sample Size	Maximum Ø100 mm